

Care and Maintenance

Oculus Quest 1:

- Use a dry optical lens microfiber cloth to clean the lenses. Wipe gently in a circular motion, moving from the center outwards. **Never** use liquid cleaners, alcohol, or soap on the lenses.
- Never leave the headset with lenses facing direct sunlight, as this will cause permanent, irreversible screen damage.
- Use a dry microfiber cloth to wipe the exterior body and the 4 tracking sensors.
- Use non-abrasive, alcohol-free antibacterial wipes for the straps and face pas.
- The facial interface foam can be removed and hand-washed with cool water and mild soaps, then left to air dry completely.
- Wipe down controllers with a dry cloth or non-abrasive, alcohol-free antibacterial wipes.
- Store the headset in a cool, dark, and enclosed case, especially if near windows.
- If you wear glasses, use the glasses space provided to prevent lens scratching.
- Insert and remove cables carefully to avoid damaging the ports.

Oculus Quest 2:

- Look above, many of the requirements for the Oculus Quest 1 also apply to the Oculus Quest 2.
- Gently clean the 4 exterior cameras with a microfiber cloth.

Revision #4

Created 2026-02-03 19:36:12 UTC by Admin

Updated 2026-02-03 20:55:36 UTC by Libby Ellwood